

EPA Notification of Hazardous Waste Site

158124
United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies. 810609

II #282

ILS-000-001-219

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Kerr-McGee Chemical Corporation
Street P. O. Box 25861 Room 1203
City Oklahoma City State OK Zip Code 73125

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Moss-American, Inc. (E. St. Louis Plant)

Street So. 20th Street and Falling Springs Road

City Centerville TWP St. Clair State IL Zip Code 62821 None

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Gaskin, P. C., Environmental Control
Phone (405) 270-2395

Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1904 To (Year) 1968

Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:
Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 300 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

K001

000219 JUN -981

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☒ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☒ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 311,000 C

gallons _____

Total Facility Area

square feet 85,300 S

acres _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required

Name P. C. Gaskin

Street Kerr-McGee Chemical Corp.

City Okla. City, State OK Zip Code 73125

Signature

Date

6/8/81

- ☐ Owner, Present
☒ Owner, Past
☐ Transporter
☐ Operator, Present
☒ Operator, Past
☐ Other

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

810702

TL#461

ILS-000-001-424

1 Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name AMAX Zinc Company, Inc.

Street Route 3 and Monsanto Ave.

City Sauget,

State IL

Zip Code 62202

3 Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site AMAX Zinc Company, Inc.

Street Route 3 and Monsanto Ave.

City Sauget

County St. Clair

State IL

Zip Code 62202

2 Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) DeSelm, John, Environmental Engineer

Phone 618/274-5000

4 Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) Unknown

To (Year) 1971

5 Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☐ Organics
2. ☒ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☒ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:
Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☒ Other (Specify)

Primary Zinc

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000001 JUL-281

AMAX Zinc Company, Inc.
P. O. BOX 2347 EAST ST. LOUIS, ILLINOIS 62202
SUBSIDIARY OF AMAX, INC.

May 27, 1981

USEPA, Region V
Sites Notification
Chicago, Illinois 60604

Dear Sirs:

AMAX Zinc Company, Inc. has owned the primary electrolytic zinc refinery located in Sauget, Illinois since 1972. Since AMAX's purchase, no storage, treatment, or disposal of "hazardous waste" has occurred on the facility property nor has AMAX accepted "hazardous waste" for transport and selected a hazardous waste TSD site. As such, we do not feel a need to submit a site notification as required by the "Superfund" Act.

However, prior to 1972, the refinery was owned by the American Zinc Company. They had a practice of storing on site, in impoundments, a residue from their leaching operations for eventual sale. As part of AMAX's purchase agreement, the stored leach residue was sold and removed by American Zinc prior to AMAX's acquisition.

Though there is a question as to whether or not first this material is a waste, and second, if a waste, whether or not the material is exempt from notification by the Solid Waste Disposal Act Amendments of 1980, we felt we should report any possible past "hazardous waste" practice to your office.

If any questions arise, please contact John DeSelm or myself at 618/274-5000.

Sincerely,

ROWigger
R.O. Wigger
Plant Manager

ROW/cal
Enclosures

SDMS US EPA REGION V

COLOR-RESOLUTION - 2

IMAGERY INSERT FORM

The following page(s) of this document include color or resolution variations. Unless otherwise noted, these pages are available in monochrome. The original document is available for viewing at the Superfund Records Center.

SITE NAME	SAUGET AREA 1
DOC ID #	158124
DESCRIPTION OF ITEM(S)	MAP
PRP	Amax, Continental Forest Industries, Kerr McGee Corp., Mobil Oil Corp., RMD - Sauget Area 1
DOCUMENT VARIATION	<input type="checkbox"/> COLOR OR <input checked="" type="checkbox"/> RESOLUTION
DATE OF ITEM(S)	N. D.
NO. OF ITEMS	1
PHASE	PRP, PRPENF
OPERABLE UNITS	
PHASE (AR DOCUMENTS ONLY)	<input type="checkbox"/> Remedial <input type="checkbox"/> Removal <input type="checkbox"/> Deletion Docket <input type="checkbox"/> Original <input type="checkbox"/> Update # <input type="checkbox"/> Volume <input type="checkbox"/> of <input type="checkbox"/>
COMMENT(S)	
CAHOKIA QUADRANT	

STATE OF ILLINOIS

DEPARTMENT OF REGISTRATION AND EDUCATION

GEOLOGICAL SURVEY DIVISION

CAHOKIA QUADRANGLE

ILLINOIS - MISSOURI

7.5 MINUTE SERIES (TOPOGRAPHIC)

TO INTERSTATE 270

TY

746

10'

17 MI TO INTERSTATE 270
4.9 MI TO ILL. 17

3) GRANITE CITY 7 MI
BRIDGLEY 2.7 MI

749 510000 FEET (ILL.)



United States
Environmental Protection
Agency
Washington DC 20460

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

Zip Code 40214

County

State III

Zip Code 62201

Phone: (203) 661-2233

From (Year) ? To (Year) still active 1981

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☒ Paper/Printing
6. ☐ Leather/Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

[illegible]

000007 JUN 22 81

Form Approved
01/16/2009

JUN 22 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

- 1 ☐ Piles
- 2 ☐ Land Treatment
- 3 ☐ Landfill
- 4 ☐ Tanks
- 5 ☐ Impoundment
- 6 ☐ Underground Injection
- 7 ☐ Drums, Above Ground
- 8 ☐ Drums, Below Ground
- 9 ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet _____

gallons _____

Total Facility Area

square feet _____

acres _____

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other"

Osby McMillan

Name: Continental Forest Industries

Street: 51 Weaver St.

City: Greenwich State: CT Zip Code: 06830

Signature:  Date: 6/18/81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other



Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

810608

D-#183

115-000-001-212

1 Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Mobil Oil Corporation
Street P. O. Box 66568
City AMF O'Hare State IL Zip Code 60666

3 Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Mobil Oil Terminal
Street 2000 South 20th Street
City E. St. Louis County St. Clair State IL Zip Code 62202

ILD075905299

2 Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Gates, Peter - Manager Environment
Phone (312) 885-6123

4 Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1917 To (Year) 1971

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☒ Other (Specify)

See "I" on reverse

Source of Waste:
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☒ Other (Specify)
Petroleum Refining

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000086 JUN -8 81

Notification of Hazardous Waste Site

Side Two

Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) See "I" below

Total Facility Waste Amount

cubic feet Unknown

gallons _____

Total Facility Area

square feet _____

acres 2 - estimated

A

Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Known

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Petroleum Refining was once conducted at this location, which is now a Petroleum Marketing Terminal. Leaded sludge (RCRA # K052) was disposed of and one or more of the other four RCRA listed petroleum refining wastes (K048-K051) may have been stored, treated or disposed. In addition, it is possible that hazardous wastes, other than those listed above, may have been stored, treated or disposed on site.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify, check "Other".

Name Mobil Oil Corporation

Street P. O. Box 66568

City AMF O'Hare State IL Zip Code 60666

Signature  Date 6/3/81
P. D. Gates, Manager, Environment & Conservation

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other